

## MOMENTSPESIFIKATIONER

RÖRMÅTT Ø	ANTAL OMDRENINGER	TILSPÄNDINGSMOMENT
8 mm	1 1/2	-0 / +1/3
10 mm	1 1/2	-0 / +1/3
12 mm	1 1/2	-0 / +1/3
15 mm	1	-0 / +1/3
18 mm	1	-0 / +1/3
22 mm	1	-0 / +1/3
28 mm	3/4	-0 / +1/3
35 mm	3/4	-0 / +1/3
42 mm	3/4	-0 / +1/3
54 mm	3/4	-0 / +1/3

## MAXIMAL ARBETSTEMPERATUR OCH TRYCK

TEMPERATUR	TRYCK
30° C	16 BAR
65° C	10 BAR
110° C	6 BAR
120° C	5 BAR